



Lead Service Line Inventory Template

Water System Name: **Chebanse PWS** System ID Number: **IL0754240** Current Inventory Date: **02/17/2026** Previous Inventory Date: **03/25/2025** Has Funding Assistance Been Requested?: **No**

Service Address	Is this a high-risk Facility or Area?	Service Line Newly Identified Since Last Submitted Inventory	Year PWS-Owned Service Line was Installed	Year Customer Side Service Line was Installed	Source of Information Used for Service Line Identification	Gooseneck/ Pigtail	PWS-Owned Service Line Material	Customer Side Service Line Material	Was Galvanized Service Line Material ever downstream of Lead?	Date Customer Notified of Lead Service Line	Was a Lead Service Line Previously Replaced at this Location?	Date Lead Service Line Replaced	Material of Service Line Replacement	Has the customer refused access to the property?	Date of customer waiver or IDPH notification, if customer refused access to property
	EXAMPLES: Group Homes, Parks, Playgrounds, Special Care Facilities, Hospitals, Clinics, Child Care Facilities	Yes (Y) or No (N)	What year was the PWS-Owned service line installed, if known?	What year was the customer side service line installed, if known?	How was the Material of this Service Line Identified? EXAMPLES: Construction Records, Visual Inspections, Survey Response, Maintenance Records, etc...	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	EXAMPLES: Copper - No Lead Solder (C) Copper - Lead Solder (CLS) Galvanized (G) Galvanized Requiring Replacement (GRR) Lead (L) Cast/Ductile Iron or Transite (O) Plastic - PVC, HDPE, PEX (P) Unknown (U) Unknown Not Lead (UNL)	If any galvanized service line material was ever downstream of a Lead section, mark Yes (Y). If the galvanized service line material was never downstream of any Lead section, mark No (N). If Yes, that section of service line should be marked as Galvanized Requiring Replacement in the appropriate immediately preceding column(s).	Enter date customer was notified of Lead Service Line. / If Service Line is not Lead put N/R	Yes (Y) or No (N)	If previous column was marked (Y), provide date the Lead Service Line was replaced. / Leave blank if previous column was (N).	EXAMPLES: Copper - No Lead Solder (C) Galvanized (G) Plastic - PVC, HDPE, PEX (P) Cast/Ductile Iron or Transite (O) Leave blank if no Lead Service Line was replaced.	Yes (Y) or No (N)	If customer refused access to property, date waiver obtained by PWS or date PWS notified IDPH of refusal to sign waiver. / Leave blank if customer has not refused access.
125 E. Chebanse Ave. #1, Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	P	P	N	N/R	N			N	
125 E. Chebanse Ave. #2, Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	P	P	N	N/R	N			N	
155 E. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
195 E. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey/Visual/Photos	C	C	C	N	N/R	N			N	
100 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
115 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
117 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
123 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
139 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
145 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
148 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
149 W. Chebanse Ave., Chebanse, 60922	N	N	1977	1977	Survey/Visual/Photos	C	C	P	N	N/R	N			N	
155 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey	C	C	C	N	N/R	N			N	
211 W. Chebanse Ave., Chebanse, 60922	N	N	2014	2014	Visual Inspections/photos	P	P	P	N	N/R	N			N	
231 W. Chebanse Ave., Chebanse, 60922	N	N	1958	2010	Visual Inspections/photos	C	P	C	N	N/R	N			N	
241 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
242 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey/Visual/Photos	C	P	P	N	N/R	N			N	
261 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey	C	C	P	N	N/R	N			N	
262 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Visual Inspections/photos	C	C	C	N	N/R	N			N	
291 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	P	P	N	N/R	N			N	
300 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey/Visual/Photos	C	C	C	N	N/R	N			N	
313 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
320 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
321 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey/Visual/Photos	C	C	C	N	N/R	N			N	
326 W. Chebanse Ave., Chebanse, 60922	N	N	1949	1949	Survey/Visual/Photos	C	C	C	N	N/R	N			N	
333 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
336 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
338 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
349 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
352 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	
357 W. Chebanse Ave., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N			N	

147 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
160 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
187 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
191 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
192 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Survey	C	C	C	N	N/R	N					N
221 Park St., Chebanse, 60922	N	N		2006	2006	Survey	C	C	C	N	N/R	N				N
241 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	P	P	P	N	N/R	N					N
261 Park St., Chebanse, 60922	N	N		1993	1993	Survey	P	P	P	N	N/R	N				N
280 Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	P	N	N/R	N					N
281 Park St., Chebanse, 60922	N	N		1995	1005	Survey	P	P	P	N	N/R	N				N
123 E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
133 E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
151 E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
153A,B,C E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	P	N	N/R	N					N
197 E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
225 E. Part St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	P	N	N/R	N					N
227 E. Park St., Chebanse, 60922	N	N		2006	2006	Survey	C	C	C	N	N/R	N				N
229 E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	P	P	P	N	N/R	N					N
255 E. Park St., Chebanse, 60922	N	N		1949	1949	Survey	C	C	C	N	N/R	N				N
256 E. Park St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
315 Peach St., Chebanse, 60922	N	N		1989	1989	Survey	C	C	C	N	N/R	N				N
327 Peach St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
445 Peach St., Chebanse, 60922	N	N		1964	1964	Survey/Visual/Photos	C	C	P	N	N/R	N				N
463 Peach St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
485 Peach St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
495 Peach St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
330 School St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	P	N	N/R	N					N
340 School St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	P	N	N/R	N					N
345 & 347 School St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
350 School St., Chebanse, 60922	N	N		1975	1975	Survey	C	C	C	N	N/R	N				N
465 & 467 School St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	P	P	N	N/R	N					N
475 School St., Chebanse, 60922	Y	N		1957	1957	Visual Inspections/photos	O	O	O	N	N/R	N				N
510 School St., Chebanse, 60922	N	N		1986	1986	Survey/Visual/Photos	C	C	C	N	N/R	N				N
120 Scott St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
130 Scott St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
165 Scott St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
195 Scott St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
154 E. Second North St., Chebanse, 60922	N	N		1949	1949	Visual Inspections/photos	C	C	P	N	N/R	N				N
196 E. Second North St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
211 E. Second North St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
116 E. Second South St., Chebanse, 60922	N	N		1950	1950	Survey	C	C	C	N	N/R	N				N
125 E. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
126 E. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
156 E. Second South St., Chebanse, 60922	N	N		2003	2003	Survey	C	C	P	N	N/R	N				N
196 E. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
115 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
188 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
213 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	P	P	N	N/R	N					N
215 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
236 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
245 W. Second South St., Chebanse, 60922	N	N		1960	1960	Survey	C	C	C	N	N/R	N				N
265 W. Second South St., Chebanse, 60922	N	N		1966	1966	Survey	C	C	C	N	N/R	N				N
320 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
325 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	P	N	N/R	N					N
330 W. Second South St., Chebanse, 60922	N	N		1957	1957	Survey	C	P	P	N	N/R	N				N
345 W. Second South St., Chebanse, 60922	N	N		1950	1950	Visual Inspections/photos	C	P	P	N	N/R	N				N
350 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
355 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
360 W. Second South St., Chebanse, 60922	N	N		1960	1950	Survey	C	C	C	N	N/R	N				N
365 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N
370 W. Second South St., Chebanse, 60922	N	N	Unknown	Unknown	Visual Inspections/photos	C	C	C	N	N/R	N					N

